

# RACCORDERIA A SALDARE

CURVE A SALDARE 90° DIMA 3	
21	76,1
26,9	88,9
30X2	101,6
33,7	108
38X2	114,3
42,4	133
44,5	139,7
48,3	159
51	168,3
54	193,7
57	219,1
60,3	244,5
63	273
70	323,9



CURVE AMBURGHESI AMPIO RAGGIO DIMA 5
27
33,7
42,4
48,3
60,3
76,1
88,9
101,6
114,3



CURVE A SALDARE 180° DIMA 3
33
42
48
60
76
89



CURVE A SALDARE 180° DIMA 5
27
33
42
48
60



FONDELLI A SALDARE	
1"	5"
1"1/4	159
1"1/2	168
2"	193
2"1/2	219
3"	244,5
3"1/2	273
4"	323
4"1/2	

## MANICOTTI



1/8
1/4
3/8
1/2
3/4
1"
1"1/4
1"1/2
2"
2"1/2
3"
3"1/2
4"
5"
6"



## TRONCHETTI

1/4
3/8
1/2
3/4
1"
1"1/4
1"1/2
2"
2"1/2
3"
4"
5"

